



100 वर्षों तक स्वस्थ,
सुखी व सम्पन्न जीने के लिए



JEENA SIKHO LIFECARE LIMITED

REGD OFFICE: ZIRAKPUR, SCO 11, Kalgidhar Enclave, Baltana, 98283-91602, 98764-03632

KOTA : 1-C-3, SFS, Sheela Choudhary Road, Talwandi, Kota, Rajasthan, 95836-95830

Email ID.: Shuddhihospitalkota@jeenasikho.co.in

Ref. No.

Dated 26/12/22

NC13/FMS1D: We had conducted this facility round on 15th December 2022 and found 02 short comings i.e. uneven area at entrance stairs which got repaired (Pic Attached) and Staff was lacking about the basic fire safety measures for which we had conducted a training on 17th December 2022 by Medical Superintendent Dr. Yogesh in which he explained the staff about basic rules of Fire Exit, Usage of Fire Extinguisher & Hose Reel.

- As you had guided us as per NABH Accreditation 2nd Edition 2016 to conduct facility inspection rounds twice a year in patient area and once a year in non-patient care area keeping in view the safety of patient and staff. We decided that we will conduct facility inspection rounds once in a month both in patient care area and non-patient care area.
- We had conducted this facility round on 15th December 2022 and found 02 short comings i.e. uneven area at entrance stairs which got repaired (Pic Attached) and Staff was lacking about the basic fire safety measures for which we had conducted a training on 17th December 2022 by Medical Superintendent Dr. Yogesh in which he explained the staff about basic rules of Fire Exit, Usage of Fire Extinguisher & Hose Reel (Pic Attached)

for
26/12/22
S. O. A. N.
JEENA SIKHO LIFECARE LTD.
1-C-3, SFS Sheela Choudhary Road
Talwandi, Kota Rajasthan-324005



100 वर्षों तक स्वस्थ,
सुखी व सम्पन्न जीने के लिए



JEENA SIKHO LIFECARE LIMITED

REGD OFFICE: ZIRAKPUR, SCO 11, Kalgidhar Enclave, Baltana, 98283-91602, 98764-03632

KOTA: 1-C-3, SFS, Sheela Choudhary Road, Talwandi, Kota, Rajasthan, 95836-95830

Email ID.: Shuddhihospitalkota@jeenasikho.co.in

Ref. No. JSLL/KT

Dated 15/12/2022

Checklist for Patient Care Areas and Non-Patient Care Areas

S. No.	Points to be checked	Yes / No / NA	Remark
1.	Is the floor slippery and probable to cause slip falls?	No	—
2.	Is there some uneven areas that can potentially cause trip fall?	Yes	—
3.	Can the gradient and height of ramps/stairs cause fall while walking through them?	No	—
4.	Does the elevators shows any sign of hazard, like sudden stoppage or jerky movements?	No	—
5.	Does the placement of furniture, overhead storage, equipment etc. likely to cause accidents?	No	—
6.	Are there any unprotected electrical wirings?	No	—
7.	Does the area contains any listed hazardous materials stored in unsafe condition?	No	—
8.	Is the condition of equipment in the area likely to cause harm to patient/staff, like electric shock, burns etc.?	No	—
9.	Are there unwanted storage in a condition that can trigger fire in the area?	No	—
10.	Will there be a difficulty in accessing a fire-extinguisher in case of fire?	No	—
11.	Are the fire extinguishers available in the area expired?	No	—
12.	Will there be a difficulty in case of 'Code Red alert' and evacuating the area in case of fire	No	—
13.	Does the area lack display of emergency evacuation route?	No	—
14.	Are there obstacles in emergency evacuation routes?	No	—
15.	Does the staff lack understanding of basic fire safety measures?	Yes	—
16.	Is the exit route free of obstacle and convenient to use?	No	—

JEENA SIKHO LIFECARE LTD.
1-C-3, SFS Sheela Choudhary Road
Talwandi, Kota Rajasthan-324005



100 वर्षों तक स्वस्थ,
सुखी व सम्पन्न जीने के लिए



JEENA SIKHO LIFECARE LIMITED

REGD OFFICE: ZIRAKPUR, SCO 11, Kalgidhar Enclave, Baltana, 98283-91602, 98764-03632

KOTA : 1-C-3, SFS, Sheela Choudhary Road, Talwandi, Kota, Rajasthan, 95836-95830

Email ID.: Shuddhihospitalkota@jeenasikho.co.in

Ref. No. _____

Dated 15/12/2022

17.	Is fire extinguisher accessible?	No	—
18.	Does the area lack adequate lighting which can be a reason for accidents or errors?	No	—
19.	Are the swing doors unsafe for people passing through it?	No	—
20.	Are there leakages/seepages in the area, rendering it prone to infections?	No	—
21.	Are there rodents and pests in the area which can cause harm to patients/staff or materials?	No	—
22.	Can the height of ceiling cause injury to head to people with long height?	No	—
23.	Are there unwanted or unnoticed holes, breaks in the floor/ground that can be hazardous while walking?	No	—
24.	Does the terrace/higher floors lacks grills at the border, making it unsafe?	No	—
<p>Other findings and remarks</p> <p>① ⇒ Yes there some uneven areas that can Potentially Cause Trip fall.</p> <p>② ⇒ Yes Staff was Not Aware of Fire Safety Measures.</p>			

15/12/2022
JEENA SIKHO LIFECARE LTD.
1-C-3, SFS Sheela Choudhary Road
Talwandi, Kota Rajasthan-324005

Date: 17/12/2022



Ramp Stair repaired



Training about Fire Extinguisher



About Hose Reel



About Fire Exit

Jeena S K
JEENA SKIOLITECH LTD.
1-C-3, SFS, Sheela Choudhary Road,
Talwandi, Kota Rajasthan-324005