

१०० वर्षों तक स्वस्थ, सखी व सम्पन्न जीने के लिए





JAIPUR, E-19, New light Colony, Gopal Pura Mod, Under Bhaskar F Contact No.: 95726-95726, Email ID: shuddhihospital.jaipur@jeenasikho.co.in

Ref. No	Dated 9 22

NC 25/FMS 1D: Regular facility inspection rounds to ensure safety is required to be carried out. E.g. seepage in kitchen, water leakage from roofs, uneven floors, easy accessibility to the terrace, risk prone balcony in IPD area and other open areas across premises.

Remarks: Kindly upload the clear photos, taking into frame the surrounding areas and with different angels of the site

> We follow every step of the way to ensure the safety of patients and visitors as per NABH guidelines. We conduct the facility round every month to ensure that all the deficiencies are rectified in time, if any. Find below the pictures of the same for your kind reference.







Back Side of Hospital building

JAIPUR-302018 (RAJASTHAN)



१०० वर्षों तक स्वस्थ, सुखी व सम्पन्न जीने के लिए





JAIPUR, E-19, New light Colony, Gopal Pura Mod, Under Bhaskar Fly Contact No.: 95726-95726, Email ID: shuddhihospital.jaipur@jeenasikho.co.in

Ref. No.

Dated 15 9 21



We have installed fiber fencing on all the outside railings keeping in view the patient safety.





We have locked the door from the inside and put up a signage that mentions this is not a common way

> UNDER BHASKAR FLYOVER JAIPUR-302018 (RAJASTHAN)